

1/20




FIG. 1







FIG. 2






FIG. 6




FIG. 12




FIG. 10




FIG. 11A




FIG. 7




FIG. 8



FIG. 9




FIG. 11B

4/20




FIG. 13



















FIG. 14








FIG. 30





FIG. 31



9/20




FIG. 35




FIG. 36




FIG. 37




FIG. 38




FIG. 39




FIG. 40




FIG. 41

10/20






FIG. 42



12/20




FIG. 45




FIG. 46




FIG. 47




FIG. 48




FIG. 49




FIG. 50A




FIG. 50B







FIG. 51



FIG. 52






FIG. 56




FIG. 57

17/20




FIG. 58

18/20

| EDIT PHASE INFORMATION | | | | | |
|---|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|
| | PHASE 1 | PHASE 2 | PHASE 3 | PHASE 4 | PHASE 5 |
| PHASE LENGTH | 28 | 0 | 0 | 0 | 0 |
| ISOMETRICS | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| RANGE OF MOTION | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| PROPRIOCEPTION | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| ISOTONICS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <div>ISEM, ROM, PROP</div> <div>OK</div> <div>CANCEL</div> <div>RESET</div> | | | | | |

FIG. 59

| EDIT TIME PARAMETERS FOR EXERCISES | |
|--|----|
| CURRENT PHASE = PHASE 1 | |
| PHASE LENGTH | 28 |
| REST TIME BETWEEN SETS | 4 |
| REST TIME BETWEEN DAYS | 10 |
| NUMBER OF SESSIONS PER DAY | 3 |
| <div>OK</div> <div>CANCEL</div> <div>RESET</div> | |

FIG. 60

| EDIT ISOMETRIC EXERCISE PARAMETERS | |
|---|---|
| CURRENT PHASE = PHASE 1 | |
| EXERCISE SHAPE | 2 |
| <div>1 </div> <div>2 </div> <div>3 </div> <div>4 </div> | |
| CYCLE LENGTH (SECONDS) | 10 |
| NUMBER OF CYCLES/REP | 3 |
| NUMBER OF ISO REPS/ANG | 5 |
| NUMBER OF ANGLES/SET | 3 |
| ANGLE VALUES (DEGREES) | <div>1 15</div> <div>2 45</div> <div>3 75</div> |
| <div>OK</div> <div>CANCEL</div> <div>RESET</div> | |

FIG. 61

19/20




FIG. 62





FIG. 63

20/20

EDIT ISOMETRIC EXERCISE SHAPE PARAMETERS

EXERCISE SHAPE PARAMETERS FOR ANGLE 1



ANGLE 15 DEGREES
 EXTENSION TORQUE 5.000%
 FLEXION TORQUE 5.000%

TOTAL CYCLE LENGTH 48 SECONDS
 EXTENSION HOLD TIME 10
 FLEXION HOLD TIME 10
 BREAK TIME 10
 RAMP TIME 2

OK CANCEL RESET

FIG. 64

PLOT TYPE

SELECT PLOT TYPE

☒ ISOMETRIC RAW DATA
☐ ISOMETRIC COMPLIANCE
☐ ROM RAW DATA
☐ ROM MIN/MAX

OK HELP CANCEL

FIG. 65




FIG. 66